

检测报告 编号: SZXPC23001243701 日期: 2023年06月25日 第1页,共5页

客户名称: 上海亿思柯电气有限公司

客户地址: 上海市浦东新区康桥东路 1159 弄 105 号 N-7

样品名称: 35 导轨挡片

材质: 钢制

型号: OMEGA35KS

以上样品及信息由客户提供。

SZIN2306003780PC01 SGS 工作编号:

收样日期: 2023年06月16日

2023年06月16日~2023年06月25日 检测周期:

检测要求: 根据客户要求检测

检测方法: 见后续页。 检测结果: 见后续页。

检测要求	结论
欧盟 RoHS 指令 2011/65/EU 附录 II 的修正指令(EU) 2015/863-铅、汞、镉和六价铬	符合

通标标准技术服务有限公司深圳分公司 授权签名



Mescal Ye 叶晓键 批准签署人





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.go.yan. for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-no-Document.aspx.
Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Room 101-901, Plant 4 Room 101, Plant 28 Room 101, Plant 38 Room 101-501, Plant 3, Barghan (Bantian) Industrial Plant Ave., No. 430, Jánua Ruad, Bantian Community, Bantian Sheet, Longsang District, Stenders, Geargioung, China 518129 www.spsgroup.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 鄭第:518129 t (86-755) 25328888 sgs.china@sgs.com



检测报告

编号: SZXPC23001243701

日期: 2023年06月25日

第2页,共5页

检测结果:

检测部件外观描述:

样品序号	样品编号	SGS 样品 ID	样品描述
SN1	001	SZX23-0012437-0001.C001	银蓝色金属

备注:

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL= 方法检测限
- (3) ND = 未检出(< MDL)
- (4) "-" = 未规定

欧盟 RoHS 指令 2011/65/EU 附录 II 的修正指令(EU) 2015/863-铅、汞、镉和六价铬

检测方法: 参考 IEC 62321-4:2013+AMD1:2017, IEC 62321-5:2013 和 IEC 62321-7-1:2015, 采用 ICP-OES 和 UV-Vis 进行分析。

检测项目	限值	单位	MDL	001
镉 (Cd)	100	mg/kg	2	ND
铅 (Pb)	1000	mg/kg	2	ND
汞 (Hg)	1000	mg/kg	2	ND
六价铬(Cr(VI))▼	-	μg/cm²	0.10	ND

备注:

- (1) 最大允许极限值引用自RoHS指令(EU) 2015/863。
- (2) IEC 62321系列等同于 EN 62321系列。
- (3) ▼ = a. 当六价铬的浓度高于0.13 μg/cm²时,样品为阳性,即含有六价铬;
 - b. 当六价铬的浓度为ND(低于0.10 μg/cm²)时,样品为阴性,即未检测到六价铬;
 - c. 当六价铬的浓度介于0.10 $\mu g/cm^2$ 与0.13 $\mu g/cm^2$ 之间时,无法直接判定是否检测到六价铬,因不同个体的样品表面差异可能会影响测定结果。

由于未获知样品的存储条件和生产日期,样品的六价铬检测结果仅能代表测试时样品含六价铬的状态。

除非另有说明,参照 ILAC-G8:09/2019,使用简单接受(w=0)的二元判定规则进行符合性判定。除非另有说明,此报告结果仅对检测的样品负责。本报告未经本公司书面许可,不可部分复制。检测报告仅用于客户科研、教学、内部质量控制、产品研发等目的,仅供内部参考。



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/lerms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Room 101-917, Part 4 & Room 101, Part 2 & Room 101, Part 2 & Room 101, Part 3 & Room 101-91, Part 3 & Room 10



检测报告

编号: SZXPC23001243701


日期: 2023年06月25日

第3页,共5页

附件

元素检测流程图

样品按照下述流程被完全消解





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8307 1443.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443 or email: CN. Doccheck@sgs.com

Room 101-901, Pant 4 Room 101, Pant 2 Room 101, Pant 3 Room 101-901, 28-101, 38-301-501 章第:518129 www.sgsgroup.com.cn 中国 - 广东 - 混制市龙岗区坂田街道坂田社区古华森430号江濂(坂田)工业厂区厂房4号101-901, 28-101, 38-301-501 章第:518129 t(88-755) 25328888 sgs.china@sgs.com




检测报告 附件

编号: SZXPC23001243701

日期: 2023年06月25日

第4页,共5页

六价铬检测流程图





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing inspections and account is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the Attention**: To check the authenticity of testing inspections and account is an attention. To check the authenticity of testing inspections and the produced accounts at the extent of the authenticity of testing inspections and accounts and the produced accounts are accounted to the full account and the

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443 or email: GN.Doccheck@sgs.com

Room 101-901, Part 4 & Room 101, Part 2 & Room 101, Part 3 & Room 101, Part 3 & Room 101, Part 3 & Room 101-901, Part 4 & Room 101-901,



检测报告

编号: SZXPC23001243701

日期: 2023年06月25日

第5页,共5页

样品照片:



此照片仅限于随 SGS 正本报告使用 ***报告结束***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-en-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's sole responsibility is to its Cilent and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

**Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8307 1443.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN. Doccheck@sgs.com

Rom 101-911, Part 4 Rom 101, Part 2 Rom 101, Part 3 Rom 101, Part 3 Rom 101, Part 3, Jarghay (Batier) Industrie Parties (N. 430, Jhu Raud, Bantian Community, Bartier Street, Longsany (Ustrict, Steeches, Guargiong, China 51612) www.sgs.group.com.cn

中国:广东·深圳市龙岗区坂田街道城田社区吉华路430号江瀛(城田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 卓编:518129 t(88-755)25328888 sgs.china@sgs.com